

From: [Sanchez, Carlos](#)
To: [Miller, Garyg](#)
Cc: [Leos, Valmichael](#); [Meyer, John](#); [Walters, Donn](#)
Subject: RE: San Jacinto to Fact Sheet.
Date: Thursday, December 17, 2015 2:54:34 PM

Thanks Gary. CAS

From: Miller, Garyg
Sent: Thursday, December 17, 2015 2:50 PM
To: Sanchez, Carlos
Cc: Leos, Valmichael; Meyer, John; Walters, Donn
Subject: RE: San Jacinto to Fact Sheet.

Carlos,

In the NW gap area its 12-inches minimum, class A rock (80% recycled concrete, 3-inch median diameter - d_{50} , 20% filter gravel). As per final report - no geotextile - NW gap area is just outside of area covered by geotextile & geomembrane. Manual probing (approx. 30' by 30' grid) after construction confirmed thickness OK at probing locations – attached.

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

From: Sanchez, Carlos
Sent: Thursday, December 17, 2015 2:18 PM
To: Miller, Garyg; Leos, Valmichael; Meyer, John
Subject: RE: San Jacinto to Fact Sheet.

Val/Gary,
For the area where the gap is located, what did the cap design consist of, for example 6 inches of rock, 3 inches of sand, geotextile, etc. CAS

From: Miller, Garyg
Sent: Thursday, December 17, 2015 12:14 PM
To: Sanchez, Carlos; Leos, Valmichael; Meyer, John
Subject: San Jacinto to Fact Sheet.

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)



9752061

214-665-8318

miller.garyg@epa.gov